



Grease Ordinance Experiences

Chuck Bellmore

Mt. Clemens Utilities Department



Mt. Clemens Grease Trap Ordinance Language

25.000 SEWERS

25.044 GREASE TRAPS

H. INTERCEPTORS. Grease, oil and sand interceptors shall be provided when, in the opinion of the Superintendent, they are necessary for the proper handling of liquid wastes containing floatable grease in excessive amounts, or any flammable wastes, sand or other harmful ingredients; except that such interceptors shall not be required for private living quarters or dwelling units. All interceptors shall be of a type and capacity approved by the Superintendent and shall be located as to be readily and easily accessible for cleaning and inspection. In the maintaining of these interceptors, the owner shall be responsible for the proper removal and disposal, by appropriate means, of the captured material and shall maintain records of the dates and means of disposal, which are subject to review by the Superintendent. Any removal and hauling of the collected material must be performed by currently licensed waste disposal firms.



Mount Clemens Grease Discharger Survey Form

*CITY OF MOUNT CLEMENS
WASTEWATER TREATMENT PLANT
RESTAURANT SURVEY*

The City of Mount Clemens is conducting a survey of all the restaurants in the city that discharge waste into the city's sewer system. Please fill out this survey to the best of your knowledge.

Restaurant Name: _____
Contact Person (Title): _____
Phone Number: () _____
Fax Number: () _____
Address: _____


Approximate the amount of grease used per day: _____
Method(s) of disposal: _____
Approximate volume of grease trap(s): _____
Frequency of grease trap(s) clean out: _____
Company which performs grease trap service: _____
(Attach copy of receipt from most recent grease trap servicing)

List of Potential Dischargers

ESTABLISHMENT NAME ADDRESS PHONE / FAX NUMBERS	DATE SURVEY SENT	DATE SURVEY RECEIVED	COMMENTS
ADA'S PARTY STORE 293 NORTH AVENUE (810)465-3812 <i>PHILLIP L. RIVARD</i>	12/12/96 #2: 9/19/97	9/26/97	DOES NOT USE OR PRODUCE ANY GREASE WASTE.
BARB'S RAIL ROAD INN 309 CASS AVENUE	12/12/96 #2: 9/19/97		
BASTUBA CATERING 149 HURON	12/12/96 #2: 9/19/97		
BILRUS & FRIENDS 369 ½ NORTHBOUND GRATIOT (810)469-9549 <i>ROSE KOLASKI</i>	12/12/96	12/19/96	ROSE CALLED AND INFORMED ME THAT THEY DO NOT USE OR DISPOSE OF ANY GREASE WASTE (12/17/96).
BROADWAY CAFE 39 NORTH GRATIOT (810)468-6811 <i>MARK / MARIO OLGATI</i>	12/12/96	12/19/96	SHARES LINE W/16, WHICH HAD MAJOR GREASE <u>BLOCKAGE</u> . NEW BUSINESS. GREASE TO BE COLLECTED IN RENDERING TANK. B & B GREASE. NO OTHER DATA GIVEN.

Enforcement Actions:

- Send plumbing inspector
- Follow-up letter “certified mail”
- Increased enforcement



Future Enforcement

Gather evidence – Take pictures!



New Dischargers



Site plan review process



Grease trap

vs.

grease interceptor



Existing Dischargers & Strip Malls

Back to back grease traps?



Surcharges



- For extra sewer line cleaning


- For inspections and recordkeeping



- For hiring a consultant (such as **fitch**)

Role of the County Health Department

Food service establishments must have health department site plan approval.



The future of grease management!

